



SERVICE REPORT WITH PICTURES

Name of Ship: MV GOLDEN KENNEDY Date: 13-09-2017

Servcies: Repair the jib of the provision crane

Preface:

As per the request of the owner GOLDEN KENNEDY, we arranged technicians to carry out repair for the jib of the provision crane and loading test after repair as per the requirement of attending ABS surveyor at Hong Tai terminal Zhang Jiagang China. Below is the report with pictures for this service.

Illustration:



The original status of the jib



Prepared for the job



Reinforced to protect the jib from distorting



Cut the damaged area(complete by two times)



Fitted up the new material



UT test after welding under the witness of ABS surveyor



PT test after UT test under the witness of ABS surveyor



Fitted up ,welded and ground the reinforcement (double plate locating on both sides)



Loading test after repair (two places)



Loading test over 5 tons(the capacity of the crane is 4 tons)

Summary:

The test was approved and accepted by DNVGL class surveyor with satisfaction.